

Pre-arrival safety check (sample)

Sample Beach House

STATUS Complete	ITEMS CHECKED 8 / 8	PHOTO PROOF 8	COMPLETED Sep 20, 2026, 12:55 AM
Property Sample Beach House	Assigned to Sample Cleaner · cleaner@example.com		
Address 123 Example Street, Sampleton	Frequency Before every booking		
Country United States	Due Sep 21, 2026, 2:55 AM		
Type Entire home	Started Sep 20, 2026, 12:55 AM		

Checklist items

1. Fire extinguisher present & charged

Pressure gauge needle is in the green zone, pin and tamper seal intact, no visible damage. Photograph the gauge.


CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Note: Gauge in the green

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 57939b887f47a38110f34505688b128934c8e8dfef0235edb097164062c13fcd



2. Fire extinguisher within 10ft of kitchen


Mounted or placed on an exit route in or near the kitchen (within ~10 ft / 3 m), visible and unobstructed, not directly beside the stove.

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 57939b887f47a38110f34505688b128934c8e8dfef0235edb097164062c13fcd



3. Smoke detectors tested & working


Press the test button on every smoke alarm (each bedroom, hallway and every level). Photograph each alarm or the one you tested last.

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 378a781a57a9bfb43566778e3ce6c402e53fdb1a9539ae5a1e2a60fc44e6e960



4. Fire blanket in kitchen


Fire blanket is mounted in the kitchen, packaging intact and pull tabs accessible.

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 57939b887f47a38110f34505688b128934c8e8dfef0235edb097164062c13fcd



5. Emergency fire escape route posted


A floor plan showing exits, extinguisher location and the meeting point is posted where guests will see it (e.g. back of the front door).

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 57939b887f47a38110f34505688b128934c8e8dfef0235edb097164062c13fcd



6. CO detector present in sleeping areas


A carbon monoxide alarm is installed outside each sleeping area and on every level with bedrooms.

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 194f75296500335ee0172e6ccfdc875aa4a29f352cf47ec48a9c7643dd6acc57



7. CO detector tested


Press and hold the test button until the alarm sounds. Photograph the alarm after testing.

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 194f75296500335ee0172e6ccfdc875aa4a29f352cf47ec48a9c7643dd6acc57



8. CO detector within expiry date


Photograph the 'replace by' date on the back or side of each CO alarm.

CHECKED

By Sample Cleaner · cleaner@example.com on Sep 20, 2026, 12:55 AM

Photo uploaded Sep 20, 2026, 12:55 AM

SHA-256 194f75296500335ee0172e6ccfdc875aa4a29f352cf47ec48a9c7643dd6acc57



Audit trail

Sep 20, 2026, 12:55 AM	Checklist created — Sample Host
Sep 20, 2026, 12:55 AM	Photo uploaded: Fire extinguisher present & charged — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: Fire extinguisher present & charged — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: Fire extinguisher within 10ft of kitchen — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: Fire extinguisher within 10ft of kitchen — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: Smoke detectors tested & working — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: Smoke detectors tested & working — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: Fire blanket in kitchen — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: Fire blanket in kitchen — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: Emergency fire escape route posted — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: Emergency fire escape route posted — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: CO detector present in sleeping areas — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: CO detector present in sleeping areas — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: CO detector tested — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: CO detector tested — Sample Cleaner
Sep 20, 2026, 12:55 AM	Photo uploaded: CO detector within expiry date — cleaner@example.com
Sep 20, 2026, 12:55 AM	Item completed: CO detector within expiry date — Sample Cleaner
Sep 20, 2026, 12:55 AM	Checklist completed — Sample Cleaner

Declaration

I confirm that the safety checks recorded in this report were carried out at the property on the dates shown, and that the photographs are a true record of the condition observed.

Host / manager signature

Printed name

Date